



Smart
connections.

FW Update

PIKO MP plus



EN

FW Update PIKO MP plus

The screenshot shows the KOSTAL Solar Electric website. A laptop icon points to the URL <https://www.kostal-solar-electric.com/download>. The website header includes the KOSTAL logo and navigation links. A 'Download' button is highlighted. Below, a search bar is shown with 'PIKO MP plus' entered. The search results show a list of updates, with one highlighted and labeled 'Software Update'. A laptop icon points to the download path 'C:\...\Downloads'.

The diagram illustrates the setup for updating the PIKO MP plus inverter. The inverter is connected to a router, which is connected to a laptop. A browser window (e.g., Firefox / Edge) shows the IP address 'xxx.xxx.xxx.xxx' entered in the address bar. The browser window also shows the 'Inverter Webinterface' with a navigation menu including 'Home', 'Events', and 'Update'. The 'Update' button is highlighted. Below the browser window, a file download is shown with the filename 'PIKO MP plus_HMI-3-9-0' and filesize '1713 kB'.

The screenshot shows a Windows file explorer window. The 'Downloads' folder is selected, and the file 'PIKO MP plus_HMI-3-9-0_PU-APP-3-3-0_ENS-1-26-0_PAR-19-0-5.img' is highlighted. The file size is 1713 kB. The 'Offnen' (Open) button is highlighted. In the background, the 'Update' interface is visible, showing the filename and filesize, and the 'Upload' button is highlighted.



Update

Filename: PIKO MP plus HMI-3.0-0_PUAPP-3.0-0_ENS-1.26.0_PAR-19.0.5.mg
 Filesize: 17113 kB

C:\Users\henbu1\Downloads\ Durchsuchen...

complete - compatible

Component	Version	Status	Progress
HMI_FTV	1.0.0	compatible complete	100.00%
HMI_APP	3.0.0	compatible complete	100.00%
PU_FAR	0.0.0	compatible complete	100.00%
PU_APP	3.3.0	compatible complete	100.00%

Home Events Update Yield PV-Generator Live-Chart **Info**

System Information

Check version

Software Versions

#	Name	Version
0	HMI BFAP STM32F4	2.8.0
1	HMI FBL	1.4.0
2	HMI APP	3.9.0
3	HMI OEM PIKO 3.0-1 MP p	1.0.1
4	PU BFAP STM32F4	2.8.0
5	PU FBL	2.0.3
6	PU APP	3.3.0
7	PU PAR default	19.0.5
8	PU OEM VARIANT_8	1.0.4
9	ENS1 APP	1.26.0

Update

PIKO MP plus 1.5-1 - 4.6-2 - Version 3.9.0.3.0.1.26.0.19.0.5 - Software Update 03.06.2019 IMQ, 1.67 MB

Neutral

Software-Version: HMI 3.9.0 / PU-APP 3.3.0 / ENS 1.26.0 / PAR 19.0.5

